
Plan Review Summary

Building Information

Project Name:	Stanchion Installation	Floor/Room #:	Level 1
Building #:	114	Department:	Auxiliary Services
Occupancy Type:	Assembly	Budget:	9,500
Construction Type:	IIB	Type of Review:	Construction

Project Management

Project Manager:	Maria Ceballos
Architect/Engineer of Record:	Maria Ceballos
Construction Manager:	TBD
Aim Project Number:	0013-2017

Reviewer Information

Reviewer Name:	Larry Labbe	Date Received:	8/3/2016
Disposition:	Approved	Date Completed:	8/3/2016

Status Statement

Note: Installation of stanchions in the student center fast food dining area.

Review Comments:

1. Approved as drawn.

General Note:

1. Inspection requests: <http://www.ehs.gatech.edu/fire/inspection-request>
2. Hot Work Permit Request: http://www.ehs.gatech.edu/fire/permit-request/hot_work

Inspections Required:

1. Pre-Construction Meeting
2. 100% Construction, Alarm Commissioning, Sprinkler Commissioning, Certificate of Occupancy (all work complete, commissioning of systems, close-out documents, etc.)

Permits Issued:

1. Construction / Interior Renovation: 2016-CP-193
-