

## Plan Review Summary

### Building Information

Project Name:	Rimoli Structures Lab Room 106	Floor/Room #:	106
Building #:	101	Department:	College of Engineering-Aero
Occupancy Type:	Business	Budget:	\$180,000
Construction Type:	IIB	Type of Review:	Construction

### Project Management

Project Manager:	Maria del Mar Ceballos
Architect/Engineer of Record:	Maria del Mar Ceballos
Construction Manager:	Mitchell Shelton
Aim Project Number:	0019-2018

### Reviewer Information

Reviewer Name:	Cary Redman	Date Received:	12/20/2017
Disposition:	Approved w/ Additional Requirements	Date Completed:	2/8/2018

### Status Statement

Note: The Rimoli Structures Lab Room 106 renovation at Montgomery Knight.

### Review Comments:

1. Sheet E 101- Provide smoke detection in accordance with yellow book requirements.

### General Note:

1. Inspection requests: <http://www.ehs.gatech.edu/fire/inspection-request>
2. Hot Work Permit Request: [http://www.ehs.gatech.edu/fire/permit-request/hot\\_work](http://www.ehs.gatech.edu/fire/permit-request/hot_work)

### Plan / Shop Drawings Required:

1. Fire Alarm

### Inspections Required:

1. Fire Safety Office Project Kick-Off Meeting
2. 80% Ceiling, Alarm, Sprinkler (vertical penetrations, junction boxes, lights tied at corners, sprinkler and fire alarm roughed in, etc.)
3. 100% Construction, Alarm Commissioning, Sprinkler Commissioning, Certificate of Occupancy (all work complete, commissioning of systems, close-out documents, etc.)

### Permits Required:

1. Fire Alarm

### Permits Issued:

1. Construction / Interior Renovation 2017-CP-299