

Plan Review Summary

Building Information

Project Name:	Joseph Oefelein Lab Fit Up	Floor/Room #:	212
Building #:	101	Department:	College of Engineering
Occupancy Type:	Business	Budget:	\$120,000.00
Construction Type:	IIB	Type of Review:	Fire Alarm

Project Management

Project Manager:	Maria Ceballos
Architect/Engineer of Record:	Maria Ceballos
Construction Manager:	Mitchell Shelton
Aim Project Number:	0404-2017

Reviewer Information

Reviewer Name:	Cary Redman	Date Received:	1/18/2018
Disposition:	Approved w/ Additional Requirements	Date Completed:	2/5/2018

Status Statement

Note: Additional fire alarm devices associated with the renovation project of the Joseph lab.

Review Comments:

1. All alarm testing must be within a 24 hour window for occupant notification. Proper signage shall be required to be placed on all entry/exit doors. Proper signage must be picked up at the fire safety office.
2. Provide smoke detector in accordance with yellow book requirements if one is not existing at the location.

General Note:

1. Inspection requests: <http://www.ehs.gatech.edu/fire/inspection-request>
2. Hot Work Permit Request: http://www.ehs.gatech.edu/fire/permit-request/hot_work

Plan / Shop Drawings Required:

1. Fire Suppression

Inspections Required:

1. Fire Safety Office Project Kick-Off Meeting
2. 80% Ceiling, Alarm, Sprinkler (vertical penetrations, junction boxes, lights tied at corners, sprinkler and fire alarm roughed in, etc.)
3. 100% Construction, Alarm Commissioning, Sprinkler Commissioning, Certificate of Occupancy (all work complete, commissioning of systems, close-out documents, etc.)

Permits Required:

1. Fire Suppression System

Permits Issued:

1. Fire Alarm 2018-FA-016

