Plan Review Summary

151 Sixth Street, Suite 341

Atlanta, Georgia 30332 404-894-FIRE (3473)

| | Building Inform | nation | |
|-----------------------|-----------------------------|-----------------|-----------------------------------|
| Project Name: | Savant OIE Suite Doors | Floor/Room #: | 2nd Floor 211 |
| Building #: | 038 | Department: | Office of International Education |
| Occupancy Type: | Business | Budget: | \$3000 |
| Construction Type: | IIB | Type of Review: | Construction |
| | Project Manage | ement | |
| Project Manager: | FATRE SA | | |
| Architect/Engineer of | Record: Amber Chellis-Omedo | | |
| Construction Manage | er: Cristina Fannin | | |
| Aim Project Number: | 200-2019 | | |
| | Reviewer Inform | nation | |
| Reviewer Name: | Jerry Marrison | Date Received: | 4/25/2019 |
| Disposition: | Approved | Date Completed: | 4/26/2019 |
| Status Statement | | | |
| | | | |
| Note: Replacemer | nt of doors (Option 1) | | |
| Review Comments: | | | |
| | | | |
| 1. Option 1 is ap | proved | | |
| | | | |

- **General Note:**
 - 1. Inspection requests: http://www.ehs.gatech.edu/fire/inspection-request

orgia Environmental Tech Health & Safety

Fire Safety

2. Hot Work Permit Request: http://www.ehs.gatech.edu/fire/permit-request/hot_work

Inspections Required:

Georgia

- 1. Fire Safety Office Project Kick-Off Meeting
- 2. 50% Wall (Rated walls, doors, dampers, horizontal penetrations, etc.)
- 3. 80% Ceiling, Alarm, Sprinkler (vertical penetrations, junction boxes, lights tied at corners, sprinkler and fire alarm roughed in, etc.)
- 100% Construction, Alarm Commissioning, Sprinkler Commissioning, Certificate of Occupancy (all work complete, 4. commissioning of systems, close-out documents, etc.)

Permits Issued:

1. Construction / Interior Renovation

2019-CP-130