

---

## Plan Review Summary

---

### Building Information

Project Name:	Beringause Demolition	Floor/Room #:	
Building #:	046	Department:	Facilities Design & Construction
Occupancy Type:	Business	Budget:	\$411,854
Construction Type:	IVB	Type of Review:	Temporary Structure

---

### Project Management

Project Manager:	Chris Sanders
Architect/Engineer of Record:	Scott Wand, Warner Summers
Construction Manager:	William Daniels, Turner Construction
Aim Project Number:	0418-2019

---

### Reviewer Information

Reviewer Name:	Jerry Marrison	Date Received:	9/17/2019
Disposition:	Approved w/ Additional Requirements	Date Completed:	9/18/2019

---

### Status Statement

Note: Construction Trailer

### Review Comments:

1. Please make sure stairs are secured
2. Certified fire extinguisher required

### General Note:

1. Inspection requests: <http://www.ehs.gatech.edu/fire/inspection-request>
2. Hot Work Permit Request: [http://www.ehs.gatech.edu/fire/permit-request/hot\\_work](http://www.ehs.gatech.edu/fire/permit-request/hot_work)

### Inspections Required:

1. Fire Safety Office Project Kick-Off Meeting
2. Thrust Block Inspections
3. Underground Pressure Test
4. System Flush
5. Sprinkler Pipe Inspections
6. Rough-in
7. 50% Wall (Rated walls, doors, dampers, horizontal penetrations, etc.)
8. 80% Ceiling, Alarm, Sprinkler (vertical penetrations, junction boxes, lights tied at corners, sprinkler and fire alarm roughed in, etc.)
9. 100% Construction, Alarm Commissioning, Sprinkler Commissioning, Certificate of Occupancy (all work complete, commissioning of systems, close-out documents, etc.)

### Permits Issued:

1. Temporary Structure 2019-TS-300
-