

Plan Review Summary

Building Information			
Project Name:	Crosland Tower/Price Gilbert Library Renewal Dumpster Location	Floor/Room #:	South Crosland Tower Hardscapes
Building #:	100	Department:	GT D&C
Occupancy Type:	Business	Budget:	\$30M
Construction Type:	IIIB	Type of Review:	Dumpster Location
Project Management			
Project Manager:	Lindsey Cottingham		
Architect/Engineer of Record: Brian Tanner/Jeremy Khan			
Construction Manage	er: Philip Vann-Brasfield & Gorrie		
Aim Project Number:	2014-2016		
Reviewer Information			
Reviewer Name:	Jerry Marrison	Date Received:	2/13/2020
Disposition:	Approved	Date Completed:	2/18/2020
Status Statement Note: Dumpster location			
Review Comments:			
1. Approved			
General Note:			
 Inspection requests: http://www.ehs.gatech.edu/fire/inspection-request Hot Work Permit Request: http://www.ehs.gatech.edu/fire/permit-request/hot_work 			
Permits Issued:			
1. Dumpster Per	mit 2020-DL-037		