

Plan Review Summary

Building Information			
Project Name:	Harris Residence Hall FFE Refreshment- Dumpster Location	Floor/Room #:	
Building #:	011	Department:	GT Housing
Occupancy Type:	Dormitory	Budget:	\$500,000
Construction Type:	IIIB	Type of Review:	Logistics-Dumpster Location
Project Management			
Project Manager:	Polly Patton		
Architect/Engineer of	Record: SWI		
Construction Manage	er: Polly Patton		
Aim Project Number:	0439-2020		
	Reviewer Inform	ation	
Reviewer Name:	Jerry Marrison	Date Received:	6/12/2020
Disposition:	Approved	Date Completed:	6/15/2020
Status Statement			
Note: Dumpster location			
Review Comments:			
 Approved Permit good for 60 days (08/15/2020) 			
General Note:			
 Inspection requests: http://www.ehs.gatech.edu/fire/inspection-request Hot Work Permit Request: http://www.ehs.gatech.edu/fire/permit-request/hot_work 			
Permits Issued:			

1. Dumpster permit: 2020-DPL-157