

## Plan Review Summary

### Building Information

Project Name:	Daniel Lab-B03-Break Room Repair Dumpster Location	Floor/Room #:	Level B/B-03
Building #:	022	Department:	Office of Facilities Management
Occupancy Type:	Business	Budget:	\$47,384
		Type of Review:	Logistics-Dumpster Location

### Project Management

Project Manager:	Blake Baklini
Architect/Engineer of Record:	
Construction Manager:	Richard Dotson-AVS- Builders Inc.
Aim Project Number:	0369-2020

### Reviewer Information

Reviewer Name:	Jake LeJeune	Date Received:	4/12/2021
Disposition:	Approved	Date Completed:	4/21/2021

### Status Statement

Note: Dumpster permit good for duration of project

### General Note:

1. Inspection requests: <http://www.ehs.gatech.edu/fire/inspection-request>
2. Hot Work Permit Request: [http://www.ehs.gatech.edu/fire/permit-request/hot\\_work](http://www.ehs.gatech.edu/fire/permit-request/hot_work)

### Permits Issued:

1. Dumpster: 2021-DPL-079