

---

## Plan Review Summary

---

### Building Information

Project Name:	John Christian Lab Dumpster Location	Floor/Room #:	G13
Building #:	041	Department:	College of Engineering
Occupancy Type:	Business	Budget:	\$123,000
		Type of Review:	Logistics-Dumpster Location

---

### Project Management

Project Manager:	
Architect/Engineer of Record:	Bill Oswell
Construction Manager:	Mitchell Shelton
Aim Project Number:	0009-2021

---

### Reviewer Information

Reviewer Name:	Jake LeJeune	Date Received:	4/19/2021
Disposition:	Approved w/ Additional Requirements	Date Completed:	4/21/2021

---

### Status Statement

Note: Dumpster; permit good for duration of project

### Review Comments:

1. Dumpster shall not obstruct the emergency access fire-lane

### General Note:

1. Inspection requests: <http://www.ehs.gatech.edu/fire/inspection-request>
2. Hot Work Permit Request: [http://www.ehs.gatech.edu/fire/permit-request/hot\\_work](http://www.ehs.gatech.edu/fire/permit-request/hot_work)

### Permits Issued:

1. Dumpster: 2021-DPL-085
-