

Plan Review Summary

Building Information

Project Name:	Weber Building SST3(98) Roof Replacement Dumpster Location	Floor/Room #:	Roofs
Building #:	098	Department:	Facilities
Occupancy Type:	Business	Budget:	\$600,000
		Type of Review:	Logistics-Dumpster Location

Project Management

Project Manager:	William T. Oswell
Architect/Engineer of Record:	William T. Oswell
Construction Manager:	Cristina Fannin
Aim Project Number:	0063-2021

Reviewer Information

Reviewer Name:	Jake LeJeune	Date Received:	4/27/2021
Disposition:	Approved	Date Completed:	4/30/2021

Status Statement

Note: Dumpster location; permit for duration of job

General Note:

1. Inspection requests: <http://www.ehs.gatech.edu/fire/inspection-request>
2. Hot Work Permit Request: http://www.ehs.gatech.edu/fire/permit-request/hot_work

Inspections Required:

1. Fire Safety Office Project Kick-Off Meeting
2. 100% Construction, Alarm Commissioning, Sprinkler Commissioning, Certificate of Occupancy (all work complete, commissioning of systems, close-out documents, etc.)

Permits Issued:

1. Dumpster: 2021-DPL-097