

---

## Plan Review Summary

---

### Building Information

---

Project Name:	Crecine Residence Hall Renovation Dumpster Location	Floor/Room #:	All
Building #:	031	Department:	Housing
Occupancy Type:	Business	Budget:	\$400,000.00
		Type of Review:	Logistics-Dumpster Location

---

### Project Management

---

Project Manager:	Daniel Powell
Architect/Engineer of Record:	Meredith Black
Construction Manager:	
Aim Project Number:	0110-2021

---

### Reviewer Information

---

Reviewer Name:	Jake LeJeune	Date Received:	5/13/2021
Disposition:	Approved	Date Completed:	5/17/2021

---

### Status Statement

Note: Dumpster Location permitted for duration of project

### General Note:

1. Inspection requests: <http://www.ehs.gatech.edu/fire/inspection-request>
2. Hot Work Permit Request: [http://www.ehs.gatech.edu/fire/permit-request/hot\\_work](http://www.ehs.gatech.edu/fire/permit-request/hot_work)

### Permits Issued:

1. Dumpster: 2021-DPL-111
-