
Plan Review Summary

Building Information

Project Name:	Tenth and Home Building D-Remediation and Repairs-Emergency	Floor/Room #:	Floors 1-5 Residential Rooms
Building #:	180	Department:	Housing and Res Life
Occupancy Type:	Dormitory	Budget:	
		Type of Review:	Logistics-Dumpster Location

Project Management

Project Manager:	Fred Holder
Architect/Engineer of Record:	
Construction Manager:	Fred Holder
Aim Project Number:	

Reviewer Information

Reviewer Name:	Jake LeJeune	Date Received:	7/22/2021
Disposition:	Approved	Date Completed:	7/26/2021

Status Statement

Note: Dumpster Location for duration of project

General Note:

1. Inspection requests: <http://www.ehs.gatech.edu/fire/inspection-request>
2. Hot Work Permit Request: http://www.ehs.gatech.edu/fire/permit-request/hot_work

Permits Issued:

1. Dumpster: 2021-DPL-177
-